

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments  Report of a Biennial Survey by Billy S. Bryant and Greg Cates conducted on 12/09/2015.  Records indicate this facility was first licensed on 01/28/1997. The facility is currently licensed for 130 Beds with a 26 Bed Special Care Unit. Therefore the facility was surveyed for conformance with the applicable portions of the 2005 Rules for Licensing of Adult Care Homes of Seven or More Beds and applicable portions of the 1996 (1997 Revision) Edition of the North Carolina Building Code(s), Institutional Occupancy and the 1996 Rules for Licensing of Adult Care Homes of Seven or More Beds in effect at the time of initial licensure.	C 000		
C 153	Exit Door Locks-Single Hand Motion  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (h) The requirements for outside entrances and exits are: (3) All exit door locks shall be easily operable, by a single hand motion, from the inside at all times without keys; and  This Rule is not met as evidenced by: 1. Based on observation the not all exit door locks are not operable by a single hand motion. Some doors had more that one set of locking hardware or the hardware required to hand motions to unlock. This could effect occupants if the facility by delaying exiting from the rooms in the event of an emergency situation.  Findings 12/09/2015:	C 153		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 153	Continued From page 1  a. Kitchen Door to Dining Area - There are two sets of hardware on the door requiring at least two and hand motions and possible three if both are engaged in order to unlock to exit.  b. Dining Room - The hardware on the doors to the corridor requires two hand motions to unlock to exit.  c. Special Care Dining Room - The hardware on the door to the corridor requires two hand motions to unlock to exit.	C 153		
C 164	Housekeeping and Furnishings-Clean, Repaired  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (1) have walls, ceilings, and floors or floor coverings kept clean and in good repair; (2) have no chronic unpleasant odors; (3) have furniture clean and in good repair; (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1. Based on observation the facility failed to keep walls, ceilings and doors clean and in good repair as evidenced but not limited to the examples listed in the findings:  Findings on 12/09/2015: a. Beauty Shop - The ceiling paint is peeling.  b. Room - 34 - Ceiling is stained and the wall is cuffed and marred.  c. Community Shower Adjacent to Room #26 -	C 164		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 164	Continued From page 2  The lock side door stile is split.  d. Med Room Across from the Dining Room - The door has surface damage.  e. Medicine Room Door - The door has surface damage.  f. Smoking Porch - The ceiling is detaching from the joists.  g. Special Care Unit - The corridor ceiling is damaged due to damage from a water leak.  h. Pattern of ceiling HVAC Grilles and the radiation dampers above the grilles clogged with dust.	C 164		
C 166	Housekeeping-Maintained Free of Hazards  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards; (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1. Based on observation the facility is not free from hazards. Loose, detached or raised exterior surface materials are in the exit path from and exit door. Loose, detached or raised exterior surface materials in the exit path from and exit door could present a tripping hazard to occupants using the exit path.	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	<p>Continued From page 3</p> <p>Finding on 12/09/2015: a. Special Care Unit Patio - There are tiles on the patio surface in the exit path that have become detached from the subsurface, are loose and/or raised above the horizontal plane of the patio.</p> <p>2. Based on observation the storage of oxygen bottles was not maintained in a manner that kept the facility free from hazards. Oxygen bottles that are not stored in an oxygen bottle rack or otherwise restrained from falling or being knocked over may present a danger to the occupants of the facility.</p> <p>Finding on 12/09/2015 a. PPE Closet -Oxygen cylinders were found stored sitting upright and without any restraining device, storage racks or compartments.</p> <p>3. Based on observation the facility is not maintained free from hazards. The building code required clearance for electrical equipment must not be encroached upon. Obstructing access to electrical equipment could prevent quick operation if needed for an emergency situations.</p> <p>Finding on 12/09/2015: a. Kitchen Electrical Room- Electrical panel access is obstructed.</p> <p>4. Based on observation there is a failure to install and maintain plumbing piping in a safe condition. Failure to maintain or install plumbing piping in a safe condition could effect all occupants of the facility if because of the unsafe condition the domestic water supply became contaminated.</p> <p>Finding on 12/09/2015: a. Kitchen - The ice machine drain does not have</p>	C 166		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 166	Continued From page 4  the building code required 2 " minimum gap between the pipe and the floor drain..	C 166		
C 174	Bedroom Furnishings-Table, Mirror, Chairs  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (b) Each bedroom shall have the following furnishings in good repair and clean for each resident: (2) a bedside type table; (3) chest of drawers or bureau when not provided as built-ins, or a double chest of drawers or double dresser for two residents; (4) a wall or dresser mirror that can be used by each resident; (5) a minimum of one comfortable chair (rocker or straight, arm or without arms, as preferred by resident), high enough from floor for easy rising; (6) additional chairs available, as needed, for use by visitors; (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1. Based on observation some furniture was not kept in good repair and some required furnishings were not present in the resident's room.  Findings on 12/09/2015: a. Room #4 - There were two residents living in the room but only one nightstand was furnished.  b. Room #28 - There was not a chair in the resident ' s room.  c. Community Shower Adjacent to Room #26 - Remove the broken chair used for bathing	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 5  assistance. Note: Removed while surveyor was on site.	C 174		
C 175	Bedroom Furnishings-Clean Towel, Towel Bar  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND FURNISHINGS (b) Each bedroom shall have the following furnishings in good repair and clean for each resident: (7) individual clean towel, wash cloth and towel bar in the bedroom or an adjoining bathroom; and (e) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1. Based on observation the facility has failed to provide individual bathroom furnishings by not having the required quantity of furnishings for each room resident.  Finding on 12/09/2015: a. There is not an individual towel rack for each resident using the shared resident room bathrooms.	C 175		
C 184	Fire Safety-Evacuation plan  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0309 PLAN FOR EVACUATION (a) A written fire evacuation plan (including a diagrammed drawing) which has the written approval of the local Code Enforcement Official shall be prepared in large print and posted in a central location on each floor of an adult care home. The plan shall be reviewed with each resident on admission and shall be a part of the	C 184		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 184	Continued From page 6  orientation for all new staff. (f) This Rule shall apply to new and existing facilities.  This Rule is not met as evidenced by: 1. Based on observation the facility failed to provide in a central location a diagrammed drawing approved by the local code official showing in large print the evacuation routes from the a potion of the building. This could affect occupants of the building seeking information on evacuation of the building in the event of an emergency.  Finding on 12/09/2015: a. There is not an evacuation plan showing evacuation routes posted for the central corridor area of the building.	C 184		
C 189	Building Equipment Maintained Safe, Operating  SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.  This Rule is not met as evidenced by: 1. Based on observation and testing there is failure to maintain the facility's emergency fire alarm system devices and equipment in a safe operating condition. Failure to maintain fire alarm system devices and equipment in a safe and	C 189		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	<p>Continued From page 7</p> <p>operable condition could effect all occupants of the facility if the equipment did not function when and as required.</p> <p>Findings on 12/09/2015:</p> <p>a. The magnetic locks on the facility exit doors did not de-energize and release upon activation of the fire alarm.</p> <p>b. When activated the central or master override switches did not de-energize the magnetic door locks.</p> <p>2. Based on observation there is a failure to maintain the facility's fire safety equipment in a safe operating condition as evidenced by doors that do not completely close and latch. Doors are required to completely close and latch in the event of a fire in order to resist the passage of smoke or the spread of fire. All the occupants in the facility could be effected if doors do not latch and remain closed so as to limit the spread of smoke or fire to the area of origin.</p> <p>Findings on 12/09/2015:</p> <p>a. Special Care Unit - The cross corridor doors adjacent to Room #9 - One leaf of the double doors is dragging on the floor and will not close. The door also did not release from its magnetic hold open device upon activation of the fire alarm system.</p> <p>b. There is a pattern of cross corridor doors that do not completely close and latch.</p> <p>3. Based on observation there is a failure to maintain the facility's fire safety systems in a safe manner as evidenced by gaps and open penetrations in the fire resistant rated ceilings. Fire resistant rated ceilings must be free of gaps</p>	C 189		



Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>HAL070008</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING: <b>01</b>  B. WING _____	(X3) DATE SURVEY COMPLETED  <b>12/09/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>WATERBROOKE OF ELIZABETH CITY</b>		STREET ADDRESS, CITY, STATE, ZIP CODE <b>143 ROSEDALE DRIVE ELIZABETH CITY, NC 27909</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 189	Continued From page 8  and openings in order to resist the spread of fire and smoke in the event of a fire. Penetrations or holes in fire resistant rated ceilings could effect the occupants of the facility by allowing fire and smoke to spread beyond the area of origin.  Finding on 12/09/2015: a. Kitchen Electrical Room - There is an open ended pipe sleeve for the data cabling that penetrates the 1 hr. fire resistant rated ceiling.	C 189		